

Air Humidity, Temperature and Barometric Pressure Sensor Manual

The TBSHT05/TBSHTP05 is an air humidity, temperature and barometric pressure sensor with SDI-12 interface. The sensing elements are located on a PCB in the tip of the sensor. The acquisition circuit is completely over-moulded. Temperature measurement is carried out with a 0.1°C precision PT1000. Humidity measurement is based on a precision sensing element on a ceramic substrate. An additional MEMS chip measures barometric pressure. The sensor tip is protected with a replaceable filter. Each sensor is individually factory-calibrated.

With dimensions of only 100mm x 16mm, the sensor can easily be fitted into many standard radiation shields.

While the TBSHT05 measures air humidity and air temperature, the TBSHTP05 measures air humidity, air temperature and barometric pressure.



TBSHT05/TBSHTP05 air humidity, air temperature and barometric pressure sensor

Features

- Air humidity, temperature and barometric pressure sensor
- SDI-12 Interface
- Temperature resolution: 0.01°C
- Temperature accuracy tolerance: -40°C to +85°C: ±0.1°C Air humidity resolution: 0.01% RH
- Air humidity accuracy tolerance:
 0% to 90%: typ. ±2%RH, max. ±2.5%RH
 90% to 100%: typ. ±2%RH, max.
 ±3.5%RH
- Barometric pressure range: 300-1100hPa (+9000 ...-500m above sea level)
- Barometric pressure resolution: 0,02hPa
- Barometric pressure accuracy: ±1hPa
- Replacable PTFE filter cap, 10µm
- SDI-12 Standard V1.3

- Plug and Play
- 6 17V supply voltage
- Dimensions: 100 mm x 16 mm
- Operating Temperature Range:
 40°C ... + 85°C
- Excellent price-performance ratio

Target Applications

SDI-12 Sensor Networks



Air Humidity, Temperature and Barometric Pressure Sensor Manual

Contents

| 1 | INT | RODUCTION | 4 |
|----|---|---|---|
| | 1.1 1.2 1.3 1.4 1.5 | PRODUCT FEATURES CALIBRATION PLACEMENT INSTALLATION SDI-12 | 4 4 4 5 |
| 2 | APF | PLICATION EXAMPLES | 6 |
| 3 | FUN | ICTIONAL DESCRIPTION | 7 |
| | 3.1 3.2 3.3 3.4 3.5 3.6 3.7 3.8 3.9 | Overview SDI-12 Basics Sensor Identification Sensor Address Measurement Commands – Quick Reference Measurement Examples Supported SDI-12 Commands Supported Extended Commands | 7 7 8 9 9 10 12 15 |
| 4 | APF | PLICATION EXAMPLE | 16 |
| | 4.1 4.1.2 4.2 4.2 4.2. 4.3 4.3.2 | SETTING UP TBSHT05/TBSHTP05 TOGETHER WITH TBS03 Requirements Driver HARDWARE Setting up the HyperTerminal application OPERATION SDI-12 / USB converter transfer mode Auto-measurement mode | 16 16 16 16 17 17 17 |
| 5 | тос | DLS FOR TBS03 | 20 |
| 6 | TEC | HNICAL SPECIFICATIONS | 22 |
| 7 | EN | /IRONMENTAL SPECIFICATIONS | 23 |
| 8 | CA | BLE CONNECTION | 23 |
| 9 | OR | DERING INFORMATION | 24 |
| 1(|) HIS | TORY | 24 |



Air Humidity, Temperature and Barometric Pressure Sensor Manual

Tables

| Table 1 – Standard SDI-12 commands | 15 |
|--|----|
| Table 2 – Extended SDI-12 Commands | 15 |
| Table 3 – Technical specifications ATRH sensor | 22 |
| Table 4 – Technical specifications pressure sensor | 23 |
| Table 5 - Environmental Specifications | 23 |
| Table 6 – Cable Connection | 23 |
| Table 7 – Ordering Information | 24 |
| Table 8 – History | 24 |
| | |

Figures

| Figure 1 – TBSHT05/TBSHTP05 sensors connected to TBS03 SDI-12 to USB converter, setup for o | controlling / |
|---|---------------|
| testing sensors and for PC based data recording | б |
| Figure 2 – TBSHT05/TBSHTP05 sensor(s) connected to Remote Telemetry Unit or Data Recorder | 6 |
| Figure 3 – Setup | 16 |
| Figure 4 – TBS03 Transfer mode initialization using Windows Hyper Terminal | 17 |
| Figure 5 – TBSHT03 (TBSHT05/TBSHTP05), sensor response to ID command 0I! | 17 |
| Figure 6 – TBSHT03 (TBSHT05/TBSHTP05) response to Start Measurement command 0M! | 18 |
| Figure 7 – TBSHT03 (TBSHT05/TBSHTP05) response to Send Data command 0D! | 18 |
| Figure 8 –TBSHT03 (TBSHT05/TBSHTP05) response to commands 0M1! and 0D! | 18 |
| Figure 9 – Terminal v1.9b, defining Macros for mode initialization and SDI-12 commands | 20 |
| Figure 10 – Example set up of Terminal v1.9b | 21 |
| Figure 11 – RH, typical and maximum tolerance at 25°C | 22 |



Air Humidity, Temperature and Barometric Pressure Sensor Manual

1 Introduction

1.1 Product Features

TBSHT05/TBSHTP05 is based on a factory calibrated sensor chips, a low power controller and robust SDI-12 interface hardware:

- Measurement of air humidity, air temperature, barometric pressure (optional) and calculation of absolute air humidity, dew/frost point
- 5V, 1200 baud SDI-12 data interface with transient protection
- 6 17V, 10 mA/60µA sensor supply
- Sensor dimensions: 100 mm, Ø 16 mm
- Operating temperature range: -40°C ... +85°C

1.2 Calibration

Each sensor is individually factory calibrated. No user calibration is required.

1.3 Placement

Don't expose the sensor to direct sun or precipitation. Install it in a location with permanent shadow and protection from precipitation, inside a radiation shield or in an instrument shelter.

1.4 Installation

The TBSHT05/TBSHTP05 is compatible with any data logger or remote telemetry unit with SDI-12 interface. Refer to the data logger or RTU manual and to chapter 2 of this datasheet.



Air Humidity, Temperature and Barometric Pressure Sensor Manual

1.5 SDI-12

SDI-12 is a standard for interfacing data recorders with microprocessor-based sensors. SDI-12 stands for serial/digital interface at 1200 baud. It can connect multiple sensors with a single data recorder on one cable. It supports up to 60 meter cable between a sensor and a data logger.

Tekbox SDI-12 sensors have been installed in networks with cable lengths up to 200m and with up to 40 connected sensors.

The SDI-12 standard is prepared by

SDI-12 Support Group (Technical Committee) 165 East 500 South River Heights, Utah 435-752-4200 435-752-1691 (FAX) http://www.sdi-12.org

The latest standard is version V1.3 which dates from July 18th, 2005. The standard is available on the website of the SDI-12 Support Group.

More information on SDI-12 is presented in chapter 3.





2 Application Examples



Figure 1 – TBSHT05/TBSHTP05 sensors connected to TBS03 SDI-12 to USB converter, setup for controlling / testing sensors and for PC based data recording



Figure 2 – TBSHT05/TBSHTP05 sensor(s) connected to Remote Telemetry Unit or Data Recorder



3 Functional Description

3.1 Overview

The SDI-12 standard defines a set of commands to configure sensors and to initiate measurements. Upon receiving specific commands, the sensor may carry out internal tasks, respond with information on conversion time or send measurement data.

SDI-12 commands are typically ASCII strings which are generated by the data recorder/controller firmware. The TBSHT05/TBSHTP05 can be connected to a TBS03 SDI-12 to USB converter and controlled by a PC application or hyper terminal. TBS03 converts the command strings to the logic levels and baud rate specified by the SDI-12 standard. Furthermore, TBS03 handles breaks, marks and all other details of the SDI-12 protocol.

Upon receiving data or status information originated by the TBSHT05/TBSHTP05, the TBS03 extracts the corresponding ASCII strings and sends them to the USB Virtual COM Port of the PC.

In remote applications, the TBSHT05/TBSHTP05 can be connected to a data logger, a data terminal or a Radio Telemetry Unit with a SDI-12 interface.

3.2 SDI-12 Basics

The SDI-12 is a serial data communication standard for interfacing multiple sensors with a data recorder. SDI-12 uses a shared bus with 3 wires: power (+12V), data, ground Data rate: 1200 baud. Each sensor at the bus gets a unique address which is in the range ASCII [0-9, a-z, A-Z]. The default address of every sensor is ASCII[0]. When setting up a SDI-12 sensor network, every sensor needs to be configured with a unique address. This can be done using the Change Address Command. A sensor can typically measure one or more parameters. Sensor manufacturers usually specify '*Extended Commands*' to configure or calibrate sensors. These commands are specified by the manufacturer, but they follow the command structure specified by SDI-12.

A typical recorder/sensor measurement sequence proceeds as follows:

1) The data recorder wakes all sensors on the SDI-12 bus with a break.

2) The recorder transmits a command to a specific, addressed sensor, instructing it to make a measurement.

3) The addressed sensor responds within 15.0 milliseconds, returning the maximum time until the measurement data will be ready and the number of data values it will return.

4) If the measurement is immediately available, the recorder transmits a command to the sensor instructing it to return the measurement result(s). If the measurement is not ready, the data recorder waits for the sensor to send a request to the recorder, which indicates that the data is ready. The recorder then transmits a command to get the data.

5) The sensor responds, returning one or more measurement results.

SDI-12 Command Structure:

Each SDI-12 command is an ASCII string with up to 5 characters, starting with the sensor address and terminated by a "!" character.

Example:

Send Identification Command **0I!**

0 is the sensor address (sensor zero). Upon receiving this command, the sensor will send an ASCII string containing sensor address, SDI-12 compatibility number, company name, sensor model number, sensor version number and sensor serial number.



Air Humidity, Temperature and Barometric Pressure Sensor Manual

The standard process to carry out a measurement is to send a measurement request upon which the sensor responds with the time that is required to carry out the measurement and the number of data items being returned. After waiting the time that the sensor requires to carry out the measurement, the data recorder sends a *"Read Command"* to get the measurement results.

Example:

Start Measurement Command 0M1!

Sensor 0 might respond **00012** which means the measurement will take 1 second and deliver 2 values. After min. 30 seconds, the data recorder can send the *"Read Data Command"* **0D0!** to which Sensor 0 might reply **0+67.75+17.23**. +67.53+17.23 is the two measurement results which may be 67.75% air humidity level and 17.23°C air temperature.

The response string of a sensor is always in ASCII format and may contain up to 40 or up to 80 characters, depending on the type of command. Out of 40 or 80 characters, the values part of the response string may contain up to 35 or 75 characters.

3.3 Sensor Identification

The air humidity temperature sensor interface will respond with a string of the following format when sending the *"Send Identification"* command **al!**:

allcccccccmmmmmvvvxxxxx<CR><LF>

Example: 013TEKBOXVNTSHTP51.0050011<CR><LF>

| 0 | SDI-12 Sensor address |
|----------|--|
| 13 | SDI-12 version number, version 1.3 |
| TEKBOXVN | Company name |
| TSHTP5 | Model Name |
| 1.0 | Firmware version 1.0 |
| 050011 | Serial number of TBSHT05/TBSHTP05 |
| | 0 13 TEKBOXVN TSHTP5 1.0 050011 |

Remark about the model name field mmmmmm:

- For TBSHTP05: mmmmmm is TSHTP5
- For TBSHT05: mmmmmm is TBSHT5

3.4 Sensor Address

Each TBSHT05/TBSHTP05 is delivered with a default address of "0"

The TBSHT05/TBSHTP05 accepts SDI-12 addresses in the range "0" to "9", "A" to "Z" and "a" to "z". Setting the TBSHT05/TBSHTP05 address can be done using the "*Change Address Command*" **aAb!**.

Note:

• If the new address is invalid, the current address will be kept.



- The TBSHT05/TBSHTP05 will remain unresponsive for approximately 1 second while the new address is saved in the EEPROM memory.
- The TBSHT05/TBSHTP05 interface supports "?" as an address only for "Acknowledge Active" Command a!.

3.5 Measurement

The TBSHT05/TBSHTP05 sensor interface accepts the "*Start Measurement*" Command **aM!**, "*Additional Measurement*" Commands **aMn!** and "*Start Concurrent Measurement*" Command **aC!**, "*Additional Concurrent Measurement*" Commands **aCn!** for obtaining calibrated values from the probe.

The TBSHT05/TBSHTP05 sensor interface will not support the "Continuous Measurement" Command **aRn!** and "Continuous Measurement and Request CRC" Command **aRCn!**. The TBSHT05/TBSHTP05 sensor will respond with its address followed by <CR><LF> in response to this command.

The response to "Start Measurement" aM!, "Additional Measurement" Commands aMn! and "Start Concurrent Measurement" Command aC!, the "Additional Concurrent Measurement" Command aCn! reports how many sensor values will be sent. In order to receive the desired sensor values, the recorder needs to issue the corresponding "Send Data" Command(s) aDn!.

Note: The TBSHT05/TBSHTP05 sensor interface uses a format of "sign" followed by n digits (The n maximum is seven -7), followed by the decimal point, followed by m digits (The m maximum is one - 1) (+n.m) return readings.

3.6 Commands – Quick Reference

Measurement commands:

| aM! | aMC! | aC! | aCC! | measure relative humidity [%] |
|-------------|-----------|------|-------|---|
| aM1! | aMC1! | aC1! | aCC1! | measure relative humidity [%] / temperature [°C] or [F] |
| aM2! | aMC2! | aC2! | aCC2! | measure temperature [°C] or [F] |
| aM3! | aMC3! | aC3! | aCC3! | approximate calculation of dew point [°C] or [F] (*) |
| aM4! | aMC4! | aC4! | aCC4! | measure relative Humidity (%) / temperature / dew point [°C] or[F] (*) |
| aM5! | aMC5! | aC5! | aCC5! | approximate calculation of absolute humidity [g/m ³] (*) |
| aM6! (*) | aMC6! | aC6! | aCC6! | estimate cloud base [m] (estimation; cannot replace a ceilometer measurement) |
| aM7! | aMC7! | aC7! | aCC7! | rel.humidity/temperature/dew point/frost point/abs. humidity/estd. cloud base (*) |
| aM8! | aMC8! | aC8! | aCC8! | Pressure [Pa] and altitude[m] (*) |
| (*) TBSH | TP05 only | | | |

Extended SDI-12 commands:

| aXSNnnnnnn! | Set serial number (6 digits) |
|-------------|--|
| aXC! | temperature unit Celsius (default factory setting) |
| aXF! | temperature unit Fahrenheit |





3.7 Measurement Examples

aM!, aC!, aMC!, aCC!: Measure Relative Humidity [%]

| Command | Response | Comment |
|---------|--------------------------------|---------|
| aM! | a0011 <cr><lf></lf></cr> | |
| aD0! | a+hh.hh <cr><lf></lf></cr> | |
| | Ex: 0+52.66 <cr><lf></lf></cr> | |

Value hh.hh: Relative Humidity

aM1!, aC1!, aMC1!, aCC1! Measure Relative Humidity [%] and Air Temperature [°C]

| Command | Response | Comment |
|---------|---------------------------------------|---|
| aM1! | a0012 <cr><lf></lf></cr> | |
| aD0! | a+hh.hh+tt.ttt <cr><lf></lf></cr> | The sign will change to – for negative temperatures |
| | Ex: 0+52.76+25.820 <cr><lf></lf></cr> | |

Value hh.hh: Relative Humidity

Value tt.ttt: Air Temperature value

aM2!, aC2!, aMC2!, aCC2! : Measure Air Temperature [°C]

| | | - |
|---------|---------------------------------|---|
| Command | Response | Comment |
| aM2! | a0011 <cr><lf></lf></cr> | |
| aD0! | a+tt.ttt <cr><lf></lf></cr> | The sign will change to – for negative temperatures |
| | Ex: 0+25.806 <cr><lf></lf></cr> | |

Value tt.ttt: Air Temperature value

aM3!, aC3!, aMC3!, aCC3! : Measure Dew Point

| Command | Response | Comment |
|---------|--------------------------------|---|
| aM3! | a0011 <cr><lf></lf></cr> | |
| aD0! | a+dd.dd <cr><lf></lf></cr> | The sign will change to – for negative temperatures |
| | Ex: 0+15.28 <cr><lf></lf></cr> | |

The approximate calculations of dew point and absolute humidity are based on the measured values of air temperature and relative humidity and on the Magnus formula:

T_K: Temperature in Kelvin [K]

Pvsat: saturated vapour pressure [hPa]

R_H: relative humidity [%]

T: Temperature [°C]

T_D: dew point temperature [°C]

P_V: vapour pressure [hPa]

C_E: estimated cloud base [m]

Parameters:

a = 7.5, b = 237.3 for T >= 0 a = 7.6, b = 240.7 for T < 0 above water (dew point) a = 9.5, b = 265.5 for T < 0 above ice (ice point)



Air Humidity, Temperature and Barometric Pressure Sensor Manual

 $\begin{array}{l} {\sf R}^* = 8314.3 \; J/(kmol^*{\sf K}) \; (molar \; gas \; constant) \\ {\sf m}_w = 18.016 \; kg \; (molecular \; weight \; of \; water \; vapour) \\ {\sf A}_{\sf H} = absolute \; humidity \; in \; g \; water \; vapour \; per \; m^3 \; of \; air \\ {\sf Formulas:} \\ {\sf P}_{Vsat} = 6.1078 \; * \; 10^{((a^*{\sf T})/(b+{\sf T})) \\ {\sf P}_{V} = ({\sf R}_{\sf H} \; /100) \; * \; {\sf P}_{Vsat} \\ {\sf T}_{\sf D} = (b \; * \; v)/(a{\sf -}v) \; where \; v = log10({\sf P}_{V} \; / \; 6.1078) \\ {\sf T}_{\sf K} = {\sf T} + 273.15 \\ {\sf A}_{\sf H} = \; 10^{\rm A}5 \; * \; (m_w \; / \; {\sf R}^*) \; * \; ({\sf P}_{V} \; / \; {\sf T}_{\sf K}) \\ {\sf C}_{\sf E} = ({\sf T}{\sf -}{\sf T}_{\sf D}) \; * \; 120 \\ \end{array}$

aM4!, aC4!, aMC4!, aCC4! : Measure Relative Humidity [%], Air Temperature [°C] and Dew Point [°C]

| Command | Response | Comment |
|---------|---|---|
| aM4! | a0013 <cr><lf></lf></cr> | |
| aD0! | a+hh.hh+tt.ttt+dd.dd <cr><lf></lf></cr> | The sign will change to – for negative temperatures |
| | Ex: 0+52.25+25.806+15.27 <cr><lf></lf></cr> | |

Value hh.hh: Relative Humidity Value tt.ttt: Air Temperature Value dd.dd: Dew Point

| aM5!, aC5!, aMC5!, aCC5! : approximate calculation of absolute humidity [g/m3 |
|---|
|---|

| Command | Response | Comment |
|---------|--------------------------------|---------|
| aM5! | a0011 <cr><lf></lf></cr> | |
| aD0! | a+www.ww <cr><lf></lf></cr> | |
| | Ex: 0+12.51 <cr><lf></lf></cr> | |

Value www.ww: Absolute Humidity

aM6!, aC6!, aMC6!, aCC6! : estimate cloud base [m] (estimation; cannot replace a ceilometer measurement)

| Command | Response | Comment |
|---------|----------------------------------|---------|
| aM6! | a0011 <cr><lf></lf></cr> | |
| aD0! | a+ccccc.cc <cr><lf></lf></cr> | |
| | Ex: 0+1266.93 <cr><lf></lf></cr> | |

Value ccccc.cc: Estimate Cloud Base

aM7!, aC7!, aMC7!, aCC7! : Humidity, Temperature, DewPoint, FrostPoint, absolute humidity and estimate cloud

| Command | Response | Comr | ment | | | | | |
|---------|---|------|------|------|--------|----|---|-----|
| aM7! | a0016 <cr><lf></lf></cr> | | | | | | | |
| aD0! | a+hh.hh+tt.ttt+dd.dd+ff.ff+www.ww+ccccc.cc <cr><lf></lf></cr> | The | sign | will | change | to | _ | for |



Air Humidity, Temperature and Barometric Pressure Sensor Manual

| Ex: 0+52.01+25.793+15.18+15.18+12.48+1274 <cr><lf></lf></cr> | negative temperatures |
|---|-----------------------|
|---|-----------------------|

Value hh.hh: Humidity Value tt.ttt: Air Temperature Value ff.ff: Frost Point Value www.ww: Absolute Humidity Value dd.dd: Dew Point Value ccccc.cc: Estimate Cloud Base

aM8!, aC8!, aMC8!, aCC8! : Pressure [Pa] and absolute altitude[m]

| Command | Response | Comment |
|---------|--|--|
| aM8! | a0012 <cr><lf></lf></cr> | |
| aD0! | a+pppppp.p+ll.ll <cr><lf> Ex: 0+100978.6+28.88<cr><lf></lf></cr></lf></cr> | The sign will change to – for negative value |

Value pppppp.p: Pressure Value II.II: Absolute Altitude

3.8 Supported SDI-12 Commands

Following commands are supported by the TBSHT05/TBSHTP05:

| Command | Description | Response |
|---------|--|--|
| a! | Acknowledge Active | a <cr><lf></lf></cr> |
| al! | Send Identification | 013TEKBOXVNTSHTP5vvvxxxxx <cr><lf> (TBSHTP05) 013TEKBOXVNTBSHT5vvvxxxxx<cr><lf> (TBSHT05) Identification information</lf></cr></lf></cr> |
| aAb! | Change Address | b <cr><lf> Changing the probe sensor address</lf></cr> |
| ?! | Address Query | a <cr><lf></lf></cr> |
| aM! | Start Measurement Measures relative humidity [%] | a0011 <cr><lf> Delay (1) seconds and number of values (1)</lf></cr> |
| aM1! | Additional Measurement Measures relative humidity [%] / temperature [°C] or [F] | a0012 <cr><lf> Delay (1) seconds and number of values (2)</lf></cr> |
| aM2! | Additional Measurement Measures temperature [°C] or [F] | a0011 <cr><lf> Delay (1) seconds and number of values (1)</lf></cr> |
| aM3! | Additional Measurement Approximate calculation of dew point [°C] or [F] | a0011 <cr><lf> Delay (1) seconds and number of values (1)</lf></cr> |
| aM4! | Additional Measurement Measures relative Humidity (%) / temperature / dew point [°C] or[F] | a0014 <cr><lf> Delay (1) seconds and number of values (3)</lf></cr> |



Air Humidity, Temperature and Barometric Pressure Sensor Manual

| | Additional Measurement | a0011 <cr><lf></lf></cr> |
|---------|---|---|
| aivi5! | Approximate calculation of absolute humidity [g/m ³] | Delay (1) seconds and number of values (1) |
| aM6I | Additional Measurement | a0011 <cr><lf></lf></cr> |
| | Estimates cloud base [m] | Delay (1) seconds and number of values (1) |
| -1471 | Additional Measurement | a0016 <cr><lf></lf></cr> |
| | Rel.humidity/temperature/dew point/frost point/abs. humidity/estimated cloud base | Delay (1) seconds and number of values (6) |
| aM8! | Additional Measurement | a0012 <cr><lf></lf></cr> |
| | Pressure [Pa] and altitude[m] | Delay (1) seconds and number of values (2) |
| | Start Measurement and Request | a0011 <cr><lf></lf></cr> |
| | CRC Measures relative humidity [%] | Delay (1) seconds and number of values (1) |
| | Additional Measurement and | |
| aMC1! | Request CRC | a0012 <cr><lf></lf></cr> |
| | Measures relative humidity [%] / temperature [°C] or [F] | Delay (1) seconds and number of values (2) |
| | Additional Measurement and | a0011 <cr><lf></lf></cr> |
| aMC2! | Request CRC | Delay (1) seconds and number of values (1) |
| | Measures temperature [*C] or [F] | |
| -MC2I | Request CRC | a0011 <cr><lf></lf></cr> |
| alvics! | Approximate calculation of dew point [°C] | Delay (1) seconds and number of values (1) |
| | or [F] | |
| aMC41 | Request CRC | a0014 <cr><lf></lf></cr> |
| | Measures relative Humidity (%) / | Delay (1) seconds and number of values (3) |
| | Additional Measurement and | |
| 2MC51 | Request CRC | a0011 <cr><lf></lf></cr> |
| awos: | Approximate calculation of absolute | Delay (1) seconds and number of values (1) |
| | Additional Measurement and | |
| aMC6! | Request CRC | autrix (1) seconds and number of values (1) |
| | Estimates cloud base [m] | |
| | Additional Measurement and Request CRC | a0016 <cr><lf></lf></cr> |
| aMC7! | Rel.humidity/temperature/dew point/frost | Delay (1) seconds and number of values (6) |
| | point/abs. humidity/estimated cloud base | |
| oMC81 | Additional Measurement and | a0012 <cr><lf></lf></cr> |
| alvico: | Pressure [Pa] and altitude[m] | Delay (1) seconds and number of values (2) |
| | Start Concurrent Measurement | a0011 <cr><lf></lf></cr> |
| aC! | Measures relative humidity [%] | Delay (1) seconds and number of values (1) |
| -041 | Additional Concurrent | a0012 <cr><lf></lf></cr> |
| | Measurement | Delay (1) seconds and number of values (2) |
| 1 | | |



Air Humidity, Temperature and Barometric Pressure Sensor Manual

| aC2! Additional Concurrent Measurement a0011 <cr><lf></lf></cr> | |
|---|--|
| aC2! Measurement | |
| | |
| Measures temperature [°C] or [F] | |
| Additional Concurrent | |
| aC3! Measurement a0011 <cr><lf></lf></cr> | |
| Approximate calculation of dew point [°C] Delay (1) seconds and number of values (1) or [F] | |
| Additional Concurrent | |
| aC4! Measurement Delay (1) seconds and number of values (2) | |
| temperature / dew point [°C] or [F] | |
| Additional Concurrent | |
| aC5! Measurement Approximate coloulation of checkute Delay (1) seconds and number of values (1) | |
| humidity [g/m ³] | |
| Additional Concurrent a0011 <cr><lf></lf></cr> | |
| aC6! Measurement Delay (1) seconds and number of values (1) | |
| Estimates cloud base [m] | |
| Additional Concurrent Monourrement a0016 <cr><le></le></cr> | |
| aC7! Rel humiditu/temperature/dow point/frest Delay (1) seconds and number of values (6) | |
| point/abs. humidity/estimated cloud base | |
| Additional Concurrent a0012 <cr><lf></lf></cr> | |
| aC8! Measurement Delay (1) seconds and number of values (2) | |
| Pressure [Pa] and altitude[m] | |
| Start Concurrent Measurement a0011 <cr><lf></lf></cr> | |
| Delay (1) seconds and number of values (1) | |
| | |
| Measurement and Request CRC a0012 <cr><lf></lf></cr> | |
| ACC1! Measures relative humidity [%]/ Delay (1) seconds and number of values (2) | |
| temperature [°C] or [F] | |
| Additional Concurrent a0011 <cr><lf></lf></cr> | |
| Measurement and Request CRC Delay (1) seconds and number of values (1) | |
| Measures temperature [C] of [F] | |
| Measurement and Request CRC a0011 <cr><lf></lf></cr> | |
| aCC3! Approximate calculation of dew point [°C] Delay (1) seconds and number of values (1) | |
| or [F] | |
| | |
| aCC4! Measurement and Request CRC add 14 CR > LP > | |
| temperature / dew point [°C] or [F] | |
| Additional Concurrent | |
| aCC5! Measurement and Request CRC | |
| Approximate calculation of absolute Delay (1) Seconds and number of values (1) humidity [g/m ³] | |



Air Humidity, Temperature and Barometric Pressure Sensor Manual

| | - | |
|-------|--|---|
| aCC6! | Additional Concurrent Measurement and Request CRC Estimates cloud base [m] | a0011 <cr><lf> Delay (1) seconds and number of values (1)</lf></cr> |
| aCC7! | Additional Concurrent Measurement and Request CRC Rel.humidity/temperature/dew point/frost point/abs. humidity/estimated cloud base | a0016 <cr><lf> Delay (1) seconds and number of values (6)</lf></cr> |
| aCC8! | Additional Concurrent Measurement and Request CRC Pressure [Pa] and altitude[m] | a0012 <cr><lf> Delay (1) seconds and number of values (2)</lf></cr> |
| aV! | Start Verification | a0000 <cr><lf> Not supported</lf></cr> |
| aRn! | Continuous Measurement | a <cr><lf> Not supported</lf></cr> |
| aRCn! | Continuous Measurement and Request CRC | a <crc><cr><lf> Not supported</lf></cr></crc> |

Table 1 – Standard SDI-12 commands

3.9 Supported Extended Commands

| Command | Description | Response |
|-------------|--|--------------------------|
| aXSNnnnnnn! | Set serial number (6 digits) | aX_OK <cr><lf></lf></cr> |
| aXC! | temperature unit Celsius (default factory setting) | aX_OK <cr><lf></lf></cr> |
| aXF! | temperature unit Fahrenheit | aX_OK <cr><lf></lf></cr> |

Table 2 – Extended SDI-12 Commands



Air Humidity, Temperature and Barometric Pressure Sensor Manual

4 Application Example

This chapter is a practical guide on how to set up a TBSHT05/TBSHTP05 , interface it to a PC with a TBS03 SDI-12 to USB converter and carry out measurements.

4.1 Setting up TBSHT05/TBSHTP05 together with TBS03

4.1.1 Requirements

User Interface

Any hyper terminal (e.g.: Windows Hyper Terminal, <u>Terminal V1.9B</u>, <u>RealTerm</u>) or specific application software (e.g. LabVIEW VI)

Hardware Interface

PC or laptop with USB interface and mini USB-B cable (USB cable supplied with TBS03)

4.1.2 Driver

Silicon Labs CP210x driver must be installed on PC (on CD supplied with TBS03 or download from <u>Silicon Labs</u>) Do not connect TBS03 to the PC, when starting the CP2102 driver installation process!

1) Start the driver installation executable

2) Follow the installation instructions step by step until the driver installation process is finished

3) The system may need to restart

4) Upon restart after successful driver installation (and not before), connect the TBS03 to the USB interface of the PC

5) Wait until you get the notification, that the new hardware has been installed and is ready to use.



Some terminal programs need manual COM port set up.

Open the hardware manager to check the COM port number assigned to the Silicon Labs USB bridge.

Every TBS03 device is serialized with an individual number. This enables the use of several TBS03's in parallel on a single PC or Laptop.

4.2 Hardware

- Connect the USB / SDI-12 Converter to PC via USB port.
- Connect the TBSHT05/TBSHTP05 SDI-12 interface to the TBS03 SDI-12 data Interface.



Figure 3 – Setup



Air Humidity, Temperature and Barometric Pressure Sensor Manual

4.2.1 Setting up the HyperTerminal application

- Open the hardware manager to check the COM port number assigned to the Silicon Labs USB bridge.
- Start the Windows HyperTerminal application.
- Connect to the COM Port assigned to the SDI-12 USB converter.
- Set the COM speed to 19200, 8 Bits, No Parity, 1 Stop Bit, No Handshake.
- In Settings, click "ASCII Setup" and activate "Send line ends with line feed" and "Echo typed characters locally".

4.3 Operation

4.3.1 SDI-12 / USB converter transfer mode

Every mode of TBS03 needs to be initialized with an ASCII string. Upon reception, the TBS03 will switch into the initialized mode and remain in this mode until the device receives an initialization string for another mode or the device gets disconnected. At the start up time, *"Transfer Mode"* is the default mode.

Transfer Mode initialisation:

In Windows hyper terminal, enter *run sdi recorder* and press the enter key (or <CR><LF>) The TBS03 will respond with *ACK*<*CR*><*LF*>

| 📧 tekbox - HyperTerminal | |
|-------------------------------------|--------------|
| <u>File Edit View Call Transfer</u> | <u>H</u> elp |
| 다 🖉 🚳 🖏 👘 | |
| run sdi recorder ACK | |

Figure 4 – TBS03 Transfer mode initialization using Windows Hyper Terminal

The TBS03 is now in transfer mode and ready to transfer commands to the sensor and respond data to the PC. The following screenshots show how to communicate with the TBSHT05/TBSHTP05.

TBS03: Entering *0I!* <CR><LF> will respond with the sensor ID:

TBSHT05/TBSHTP05 response: 013TEKBOXVN_TBSHT05/TBSHTP05_V0.10_000001 <*CR*><*LF*>

Upon sending the ID command **0I!**, the sensor responds with SDI-12 compatibility level, Manufacturer name, Model name, Firmware release number and serial number

| 💽 tekbox - HyperTerminal |
|---|
| <u>File E</u> dit <u>V</u> iew <u>C</u> all <u>T</u> ransfer <u>H</u> elp |
| 다 🗃 🍙 🗿 🗠 🎦 😭 |
| run sdi recorder ACK ØI! ØI3TEKBOXVN_TBSHT3_V0.10_000002 |

Figure 5 – TBSHT03 (TBSHT05/TBSHTP05), sensor response to ID command 0I!

TBS03:Entering **0M!** <CR><LF> will respond with:TBSHT05/TBSHTP05 response:00011 <CR><LF>



Air Humidity, Temperature and Barometric Pressure Sensor Manual

which means that the sensor will be able to deliver 1 value after an acquisition time of 1 second

| _ | |
|---|--|
| | tekbox - HyperTerminal |
| E | ile <u>E</u> dit <u>V</u> iew <u>C</u> all <u>T</u> ransfer <u>H</u> elp |
| С |) 🚔 🕋 🍒 💷 🎦 😭 |
| | run sdi recorder ACK 0I! 013TEKBOXVN_TBSHT3_V0.10_000002 0M! |
| | 00011 |

Figure 6 – TBSHT03 (TBSHT05/TBSHTP05) response to Start Measurement command **0M!**

TBS03:Entering 0D0! <CR><LF> will respond with:Sensor response:0+71.89 < CR><LF>where 71.89 is the measured air humidity level of 71.89%

| tekbox - HyperTerminal |
|--|
| <u>File Edit View Call Transfer Help</u> |
| D 🚔 🚎 🍒 🗈 🎦 😭 |
| rum sdi recorder ACK 0I! 013TEKBOXVN_TBSHT 3 _V0.10_000002 0M! 00011 0D0! 0+71.89 |

Figure 7 – TBSHT03 (TBSHT05/TBSHTP05) response to Send Data command OD!

TBS03: Entering **0M1!** <CR><LF> will respond with:

TBSHT05/TBSHTP05 response: 00012 <CR><LF>

which means that the sensor will be able to deliver 2 values after an acquisition time of 1 second

TBS03: Entering **0D0!** <CR><LF> will respond with:

Sensor response: 0+71.73+30.04 <CR><LF>

where 71.73 is the measured air humidity level of 71.73% and 30.04 is the air temperature of 30.04°C

| tekbox - Hyperterminal |
|---|
| <u>File Edit V</u> iew <u>Call</u> <u>Transfer</u> <u>H</u> elp |
| 다 🚔 💿 🕉 🗈 💾 😭 |
| |
| run sdi recorder |
| ACK |
| I AT I |
| 013TEKBOXVN TBSHT3 VO 10 000002 |
| |
| 00011 |
| |
| 0+71 89 |
| 0M11 |
| 00012 |
| |
| 0+71 79+90 04 |
| 0.11.10.00.04 |
| (TDOLITOF/TDOLITDOF) rearrange to a |

Figure 8 – TBSHT03 (TBSHT05/TBSHTP05) response to commands **0M1!** and **0D!**

Other SDI commands will work similarly.



Air Humidity, Temperature and Barometric Pressure Sensor Manual

4.3.2 Auto-measurement mode

Auto-measurement mode is only available on TBS03 with option OTBS03-1 or option OTBS03-2

Like SDI Transfer commands, this application sends measurement commands which are set up by the user, to the SDI-12 / USB interface. Then, it automatically collects measured data by sending aDn! commands and transfers the data via USB Interface. After that, the next measurement command is started with a user defined time interval in between consecutive measurements. The maximum timer value is 4294967295ms. The maximum number of different SDI-12 measurement commands in an auto measurement string is 9. Automeasurement mode is stopped by sending *stop* <CR><LF>

Syntax: run auto <measurement command 1> <timer value 1> ... <measurement command n> <timer value n>

Example of controlling a TBSHT05/TBSHTP05 in auto measurement mode:

TBS03: Entering *run auto 0M4!* 10000<CR><LF> will respond with periodically measured temperature, humidity and dew point (frost point) values. The time interval between two consecutive measurements is 1000ms:

run auto 0M4! 1000 ACK OM4!: 0+71.96+30.08+24.45 OM4!: 0+71.92+30.09+24.46 OM4!: 0+71.89+30.10+24.46 OM4!: 0+71.86+30.10+24.45 OM4!: 0+71.83+30.11+24.46 OM4!: 0+71.80+30.12+24.46 OM4!: 0+71.76+30.13+24.46 OM4!: 0+71.73+30.15+24.46 OM4!: 0+71.67+30.15+24.45 OM4!: 0+71.67+30.15+24.45 OM4!: 0+71.64+30.16+24.45 OM4!: 0+71.60+30.17+24.45 OM4!: 0+71.60+30.17+24.45 stop ACK



5 Tools for TBS03

The TBS03 can be controlled using hyper terminals or customized PC application software. National Instruments, for example, offers a LabView SDI-12 API which could be used for designing customized applications for TBS03.

When using Hyper Terminal programs, take care that the representation of <CR><LF> may be different for different programs.

Windows Hyper Terminal requires activatation of "Send line ends with line feed" in ASCII setup and thereafter pressing the ENTER-key results in <CR><LF>

Many Hyper Terminal programs require \n at the end of each SDI-12 string – e.g. OM!\n or run sdi recorder\n

<u>Terminal v1.9b – 20080315β – by Br@y ++</u> requires adding $0D\$ for <CR><LF>. This tool offers user defined macros for frequently used commands - a convenient feature when working with TBS03.

| Load Save old format | | | | | |
|-------------------------------------|--------|--------|------|----|---|
| Transmit Macros | | | | | |
| run sdi recorder\$0D\$0A | transp | transp | 1000 | • | Γ |
| run auto 0M! 1500 0M4! 2000\$0D\$0A | auto | auto | 1000 | - | |
| run sdi monitor\$0D\$0A | monit | monit | 1000 | \$ | Γ |
| run sdi tester\$0D\$0A | tester | tester | 1000 | \$ | Γ |
| 0!!\$0D\$0A | ID | ID | 1000 | \$ | Γ |
| 0M!\$0D\$0A | OM! | OM! | 1000 | \$ | |
| 0M1!\$0D\$0A | OM1! | 0M1! | 1000 | \$ | Γ |
| 0M2!\$0D\$0A | OM2! | 0M2! | 1000 | \$ | |
| 0M3!\$0D\$0A | OM3! | 0M3! | 1000 | \$ | Γ |
| 0M4!\$0D\$0A | OM4! | 0M4! | 1000 | \$ | |
| 0D0!\$0D\$0A | 0D0! | 0D0! | 1000 | \$ | |
| 0D1!\$0D\$0A | 0D1! | 0D1! | 1000 | \$ | |
| 0C!\$0D\$QA | 0C! | 0C! | 1000 | \$ | |
| 0C1!\$0D\$0A | 0C1! | 0C1! | 1000 | \$ | |
| 0C2!\$0D\$0A | 0C2! | 0C2! | 1000 | \$ | Г |
| | M16 | MIE | 1000 | | Г |

Figure 9 – Terminal v1.9b, defining Macros for mode initialization and SDI-12 commands



Air Humidity, Temperature and Barometric Pressure Sensor Manual

When manually entering commands in Terminal v1.9b, tick the CR=CR+LF and +CR box.

| الله المراجع (1996) - 200803156 - by Br@y++ | | × |
|--|---------------|----------|
| Disconnect COM Port Baud rate Com Composition Data bits Party Stop bits Handshaking BeScan CDM5 C 14400 C 57600 C 1400 C 57600 C 10 C 1 C none C 1 C RS/CTS C NN/XOFF About. COMs C 4800 C 38400 C 256000 C 7 C mark C 2 C RTS/CTS+X0N/XOFF Quit C 9600 C 56000 C ustom C 8 C space C 2 C RTS/CTS+X0N/XOFF | | |
| setion: Auto Dis/Connect ∏ Time ☐ Stream log outom BB Pactear ASCIttable Scripting AutoStart Script ☐ CR=LF ☐ Stay on Top 13200 27 Graph Remote | CTS C DSR | CD RI |
| Receive CleAR Reset Counter 13 Counter = 75 C HEX Dec Bin CLEAR Reset Counter 13 Counter = 75 C ASCII Hex StopLog REQ_RES | | |
| ACK <-D-013ADCON A516 024000000 <-D-00012 <-D-0+0+177 <-D-0081 <-D-0+0+0+0+0.811611+1+106+0.667428+3 <-D-0+0+0+0+0.811611+1+106+0.667428+3 <-D-0+0+0+0+0+0.811611+1+106+0.667428+3 <-D-0+0+0+0+0+0+0.811611+1+106+0.667428+3 <-D-0+0+0+0+0+0+0+0+0+0+0+0+0+0+0+0+0+0+0 | | * |
| CLEAR Send File 1 | DTR 🗖 | RTS |
| Macros transp auto monit tester ID 0M1 0M1 0M2I 0M3I 0M4I 000000 0D11 | | |
| [run sdi recorder | IV +CR _→ Set | nd |
| run sdi recorder | | ~ |
| or . | | |
| OM! | | |
| 000! | | |
| 0//4! | | |
| 000! | | |
| | | - |

Figure 10 – Example set up of Terminal v1.9b

The above mentioned Hyper Terminal Programs are just examples to highlight that using such tools requires to take care of their way to handle <CR><LF>.



Air Humidity, Temperature and Barometric Pressure Sensor Manual

6 Technical Specifications

| Symbol | Parameter | Conditions | Min | Тур | Max | Unit |
|---------------------|---|-------------------------------------|-----|-------|----------------|---------------|
| ls | Supply current | Active mode | 8 | 9 | 10 | mA |
| ls | Supply current | Sleep mode | 50 | 60 | 70 | μA |
| Vs | Supply voltage | | 6 | 12 | 17 | V |
| tm | Measurement Time | Time in active mode per measurement | | | 700 | ms |
| RH _{range} | Relative humidity measurement range | | 0 | | 100 | %RH |
| RH _{res} | Relative humidity resolution | | | 0.01 | | %RH |
| RH _{tol} | Relative humidity accuracy tolerance | | | ±2 | see fig. 11 | %RH |
| RH_{h} | Relative humidity hysteresis @ 25°C | | | ±0.8 | | %RH |
| RH _{rep} | Relative humidity repeatability | | | ±0.15 | | %RH |
| RH _{drift} | Relative humidity long term drift @25°C | | | <0.25 | | %RH / year |
| Trange | Temperature measurement range | | -40 | | +85 | °C |
| T _{res} | Temperature resolution | | | 0.01 | | °C |
| T _{tol} | Temperature accuracy tolerance | | | ±0.1 | ±0.12 | °C |
| Tres | Temperature long term drift | | | <0.04 | | °C / year |



Figure 11 – RH, typical and maximum tolerance at 25°C



Air Humidity, Temperature and Barometric Pressure Sensor Manual

| Parameter | Conditions | Min | Тур | Max | Unit |
|----------------------------|--------------|------|-------|------|------|
| Barometric prossure range | | 300 | _ | 1100 | hPa |
| Barometric pressure range | | 9000 | _ | -500 | m |
| | 950 1050 hPa | | ±0.12 | | hPa |
| Polativo prossuro accuracy | @ 25 °C | | ±1 | | m |
| Relative pressure accuracy | 700 900hPa | | ±0.12 | | hPa |
| | 25 40 °C | | ±1 | | m |
| | 300 1100 hPa | _1 | _1+1 | +2 | hPa |
| Absolute pressure accuracy | 0 +65 °C | -4 | -111 | 12 | in a |
| Absolute pressure accuracy | 300 1100 hPa | -6 | _1+1 | +4.5 | hPa |
| | -20 0 °C | -0 | -1-1 | 14.5 | in a |
| PMS poise | | | 0.03 | | hPa |
| | | | 0.25 | | m |

Table 4 – Technical specifications pressure sensor

7 Environmental Specifications

| Symbol | Parameter | Conditions | Min | Max | Unit |
|--------|--|------------|-----|-----|------|
| TA | Operating Ambient Temperature Range | | -40 | +85 | °C |
| Тѕтс | Storage Temperature Range | | -50 | +90 | °C |
| | humidity level | | 0 | 100 | % |

| Table 5 - Environmental Specifications |
|--|
|--|

8 Cable Connection

| Cable Colour | Signal Assignment |
|--------------|-------------------|
| Blue | SDI-12 Power |
| Yellow | SDI-12 Data |
| Brown | GND |
| Black | Shield (GND) |

Table 6 – Cable Connection





9 Ordering Information

| Part Number | Description |
|-------------|---|
| TBSHT05 | Air Humidity, Temperature, SDI-12 Interface |
| TBSHTP05 | Air Humidity, Temperature, Barometric Pressure sensor, SDI-12 Interface |
| ATRH_FIL | Replacement filter cap, PTFE, 10µm pore diameter |

Table 7 – Ordering Information

10 History

| Version | Date | Author | Changes |
|---------|------------|------------|--|
| V1.0 | 5.04.2015 | Mayerhofer | Creation of the document |
| V1.1 | 20.12.2019 | Mayerhofer | Table 4 update |
| V1.2 | 18.03.2020 | Mayerhofer | Update from TBSHT(P)03 to new version TBSHT(P)05 |
| | | | |
| | | | |

Table 8 – History